

Damage of Bridges due to kumamoto Earthquake

Kenji Kosa

Kyushu Institute of Technology

1. Introduction of Kumamoto Earthquake

2. Okirihata Bridge


3. Aso Bridge

4. Minami-aso Arch Bridge




5. Damage to Rocking Piers

6. Damage to Footings

1.(1) Bridges were damaged along Hinagu and Futagawa faults. Damage was caused by ground motion and ground movement.



Acceleration response spectra of Kumamoto Earthquake



- KMM004一の宮
- KMM005大津
- KMMH16益城
- 西原村小森
- Road specifications

- KMM004一の宮
- KMM005大津
- KMMH16益城
- 西原村小森
- Road specifications

- KMM004一の宮
- KMM005大津
- KMMH16益城
- 西原村小森

1.(2) Kumamoto spectra exceeds stad. spectra by Road Spec.

2. (1) Okirihata Bridge - Damage


P4 : bolt of bearing
broken.

A2 : 1 m movement
of girder


A1 : 1 m movement
of girder

P3 : bolt of
bearing broken

P1 : bolt of
bearing broken



2. (2) Okirihata Bridge - Damage



1. At A1, A2, P1, P3, P4, rubber bearings were broken.
2. At P2, cracking occurred at the column.
3. At A1, PC cable restrainers were broken.




2. (3) Okirihata - Rubber Bearing




Rubber portion of rubber bearing was broken.

Main girder moved to the transverse direction about 30cm.

2. (4) Okirihata Bridge - cable restrainer



All (10) cable restrainers were broken by the movement of girder.



Displacement-perpendicular: 1105 mm

Displacement-longitudinal: 350 mm


2. (5) Okirihata Bridge – Damage of Rubber Bearing

1. The Rubber portion was broken into two parts.

2. Displacement between upper rubber portion and lower rubber portion was measured.

3. About 1 m displacement was observed due to the movement at substructure.

4. Rubber bearing was weak for ground movement



2. (6) Okirihata Bridge – Damage of Rubber Bearing


$h = 20\text{cm}$

Allowable displacement = $20 \cdot 300\% = 60\text{cm}$

Actual Displacement = 100cm

Rubber bearing was weak for ground movement

3.(1) Aso Bridge - Slope Failure



200m

350m

Aso bridge

Many people considered the Aso Bridge collapsed due to landslide. Was it true?

3.(2) Aso Bridge- Collapase of bridge



Accumulation of sand


Side span


Foundation

Arch rib

Collapse of bridge (main span & side span)

3.(3) Aso bridge - slope failure







3. (4) Possible cause of bridge collapse

- ① Accumulated soil by the first landslide
- ② Movement of soil by the second landslide, or
- ③ Displacement of abutment (Fault effect?)

3. (5) Possible cause of bridge collapse: ①, ② or ③




3. (6) To investigate Cause①, SPH(smoothed particle hydrodynamics) method was applied (Kiriya)



Little possibility as to Cause① (first landslide)

3.(7) Cause2 or 3: Displacement of abutment (2.2m) lead arch rib to the ultimate stage.^(che)



3. (8) We need more information.

1. How far was the arch abutment displaced?

2. How much landslide soil was accumulated around the bridge?

4. (1) Minami-aso Arch Bridge



Damper had been installed as retrofitting. Punching shear failure occurred between damper and abutment.

4. (2) Direction of movement



1. Side block was not damaged.
2. The girder beside the RC wall was not damaged, so the movement was not in the transverse direction.
3. Movement occurred in the longitudinal direction





Scratch due
to movement

4. (3) Scratch due to movement was observed.
Punching shear failure had not checked during design.

5. (1) Damage to Rocking Piers


1. Rocking piers (Kawaragi) damaged in the 1995 Kobe Earthquake.
2. Rocking piers at three bridges (Furyo, Higashihara, Takagi) were damaged in the Kumamoto Earthquake
3. We investigated the cause of failure of rocking piers.

5. (2) One rocking pier (Kawaragi) was collapsed during Kobe earthquake. P25, 26 were rocking piers.






5. (3) Skew girder rotated and fell down in the 1995 Kobe Earthquake.




5.(4) Fuyo Daiichi Bridge in Kumamoto Earthquake
 Span length was 60m. P1 & P2 were rocking columns.
 Skew girder rotated and fell down.




5. (5) Damage at Furo Daichi Bridge

1. The girder collided with the restrainers due to rotation.
2. Punching shear failure occurred at the connection of restrainer and abutment.



5. (6) Damage to rocking piers


1. Girder moved to the transverse direction.
2. Pivot type bearing was used.
3. When the rotating angle was over 0.06 rad, pivot bearing collided with plate, and leads to the collapse of the bearing.




Under dead load

Under seismic force




Pivot bearing is used at lower and upper ends.




中立時 上下沓が接触 上沓が乗り上がる



5.(7) Bearings were damaged due to large rotation.



Collide with plate and move up



5.(8)1. When rotational angle of column was 0.06rad, this value is the limit angle of pivot bearing.
2. As the restrainers were completely collapsed, the pivot bearings rotated over 0.06rad, and the bridge collapsed.

5. (9) Design problems of Furo Daiichi Bridge

1. P1, P2 were rocking columns. There was not installed for longitudinal restrainers.

There was installed for transverse restrainers to protect rotation of girder.

2. F (Acting force for transverse direction)

$3kh$ (seismic coefficient: $0.75G$), R_d (Dead load)

$$F = 3kh \cdot R_d = 1554 \text{ kN}$$

3. Actual applied acceleration would be larger than $3kh$ (about $0.75G$).

4. Punching shear resistance = 1076 kN

5. Resistance is smaller than the acted force.






5. (10) Higashihara bridge had rocking columns at P1 and P2.

The column top moved to transverse direction about 35cm.





5. (11) Damage to the Higashihara Bridge
Transverse restrainers (concrete block) were completely
damaged.
The bridge almost fell down to the national road.




5. (12) Damage to the Higashihara Bridge
 There were provided 4 transverse restrainers.
 Each side of the girder has each restrainer.
 These 4 restrainers would provide large resistance
 against seismic force.

6. (1) Damage to footings



1. Shear failure



2. Shear failure at joint



Kobe EQ (Hanshin expwy)

Kumamoto EQ (NEXCO expwy)

3. Punching shear

Kobe EQ (Hamate bypass)

6. (2) Damage to footings in Kumamoto Earthquake



Tilting of the column (3.2°) was observed.



6. (4) Characteristics of damaged footing
Low main reinforcement & small sized footing




6. (5) Damage to footings in Kobe Earthquake

3 damaged footings were found.

Cracks propagated to the radial direction.




6. (6) Cracks also propagated to the radial direction from the column.




6. (7) Fig. General structure of the damaged footing

Maximum crack width 20 mm, average crack width 7mm. Proto-type (50 % scale) test was conducted.




6. (8) Fig. Cracks observed on the footing




One-direction monotonic loading was applied.

6. (9) Fig. Test Setup

Horizontal load was increased. A vertical load was kept at 109 tf as dead load.




6. (10) Photo Test setup




6. (11) Fig. Propagation of cracks under loading

Upper concrete started to rise, and a cone-type failure was generated.



6. (12) Fig. Final failure mode of the footing



6. (13) Fig. Load-displacement relationship taken at the column top

6. (14) Results of the experiment

1. Cracks appeared at the column-footing connection.
2. Damage that determines the maximum load is the yielding of the upper reinforcement.
3. Reinforcement in the upper area of the footing is effective to increase the bearing capacity.

7. Conclusions

1. In Kumamoto Earthquake, many bridges were damaged due to the ground motion and ground movement
2. Rocking columns were weak against large seismic force.
3. Restrainer should be provided to restrain movements of the girder in the longitudinal and transverse directions.
4. Footing damage was observed. It had an effect on the tilting of columns.